

Fluxa A - Ausleger
 Flächenstrahler für Wand-
 und Mastbefestigung

8 272 3.5
8 272 3.7
8 271 3.5
8 271 3.7
8 273 3.5
8 273 3.7
8 274 3.7

Schutzart IP 65
 Schutzklasse I

t_a 25°C

MONTAGE
 ANLEITUNG
 Mounting
 instructions

WILLY MEYER & SOHN GMBH & CO.KG
 LICHTTECHNISCHE SPEZIALFABRIK
 Stemmessiepener Weg 5 • D-58675 Hemer

Flächenstrahler für Halogen-Metaldampflampen (HIT und HIT-CE) 35 W, 70 W, 150 W, Fassung G12 - und Philips CosmoPolis (HIT-CE) 45 W, 60 W, 90 W, 140 W, Fassung PGZ12.

MONTAGEHINWEISE
 Anschluß der Leuchte nach VDE 0100.
 Flächenstrahler für ungeschützte Anlagen.
 ⚠ Leuchte ist geeignet für Montage auf normal entflammaren Baustoffen.
 ⚡ Achtung Hochspannung!
 Vor dem Öffnen der Leuchte oder Lampenwechsel Netzspannung trennen.

Montage am Mastaufsatz
 Auf ausreichende Dimensionierung des Mastes achten, ggf. Rücksprache mit dem Masthersteller nehmen.
 Rahmen-Befestigungsschrauben lösen.
 Rahmen mit Glas anheben und vom Gehäuse schwenken.
 Je nach Masthöhe ausreichend lange Netzanschlußleitung durch die Kabelverschraubung führen.
 Leitung 13 cm abmanteln (Fassung G12), Leitung 9 cm abmanteln (Fassung PGZ12) und beiliegende Silikonschläuche über die Einzeladern ziehen.
ACHTUNG! Mantelleitung darf maximal 2 cm in das Leuchtengehäuse ragen.
 Elektrischen Anschluß vornehmen.
 Kabelverschraubung festdrehen.
 Lampe einsetzen, dabei auf richtige Bestückung laut Typenschild achten.
 Rahmen mit Glas auf Gehäuse schwenken und dicht verschrauben.
 Leuchte an die Schrauben M10 x 40 am Mastaufsatz einhängen und mit einem Drehmoment von 44 Nm anziehen.
 Die Gewindeeinsätze im Mastaufsatz sind selbstsichernd.
 Das Anschlußkabel durch die Bohrung im Mastaufsatz schieben und am Kabelübergangskasten im Mast anschließen.

Montage an der Wandplatte
 Auf ausreichende Befestigung der Wandplatte auf dem Montagegrund achten!
 Leuchte an die entsprechenden Schrauben M10 x 40 einhängen und die Schrauben mit einem Drehmoment von 44 Nm anziehen.
 Die Gewindeeinsätze in der Wandplatte sind selbstsichernd.
 Zuleitung durch die Kabelverschraubung in die Leuchte einführen und wie zuvor beschrieben anschließen.

Montage auf anderen Oberflächen
 Auf ausreichende Festigkeit des Montagegrundes achten. Zur Befestigung der Leuchte mind. zwei rostfreie Schrauben M10 der Festigkeit 70 verwenden und für einen ausreichenden Lockerungsschutz sorgen.
 Elektrischen Anschluß wie zuvor beschrieben vornehmen.

Das Glas ist ein Einscheiben-Sicherheits-Hartglas.




Die Leuchte darf nur mit ihren vollständigen Schutzabdeckungen betrieben werden.


Leuchte	Gewicht	Windangriffsfläche
8 272 3..	9,0 kg	0,11 m ²
8 271 3..	9,0 kg	0,11 m ²
8 273 3..	9,5 kg	0,11 m ²
8 274 3..	9,0 kg	0,11 m ²

In Strahlrichtung den Mindestabstand zu angestrahlten Flächen einhalten!

8 272 3..
 8 271 3..

8 273 3..
 8 274 3..





Fluxa A - with arm
 Area floodlight for wall-
 or pole mounting

8 272 3.5
 8 272 3.7
 8 271 3.5
 8 271 3.7
 8 273 3.5
 8 273 3.7
 8 274 3.7

Protection IP 65
 Safety Class I

t_a 25°C



MONTAGE
 ANLEITUNG
 Mounting
 instructions



WILLY MEYER & SOHN GMBH & CO.KG
 LICHTTECHNISCHE SPEZIALFABRIK
 Stemmessiepener Weg 5 • D-58675 Hemer

Area floodlight for metal halide lamps
 (HIT and HIT-CE) 35 W, 70 W, 150 W,
 lampholder G12 - and Philips
 CosmoPolis (HIT-CE) 45 W, 60 W, 90 W,
 140 W, lampholder PGZ12.

MOUNTING INSTRUCTIONS

Connect the light fitting in compliance with
 prevailing regulations in your country.
 Luminaire for non-protected outdoor
 installation.

Light fitting is suitable for installation
 on normal inflammable building materials.

Attention ! High Voltage !
 Disconnect power supply before opening
 light fitting or changing lamp.

Mounting on pole top fitter

Ensure that the correct size of pole is chosen;
 if necessary consult the pole manufacturer.

Loosen screws in front frame. Lift frame and
 glass and swing away from casing.

Depending on height of pole, take
 a sufficiently long piece of cable and
 insert it through the cable gland.

Strip the sheathing off the last 13 cm (lamp-
 holder G12), strip the sheathing off the last
 9 cm (lampholder PGZ12) of cable and
 slide the enclosed silicone sleeves over
 the ends of the individual wires.

ATTENTION ! Do not insert more than 2 cm
 of sheathed cable into luminaire housing.

Make the electrical connection.

Screw cable gland tight. Insert lamp,
 taking care to use the correct lamp as
 mentioned on the rating plate.

Swing front frame and glass back onto
 casing and screw down evenly.

Hang the luminaire onto the M10 x 40
 screws on the pole top fitter and tighten
 with 44 Nm torque. The threaded inserts
 in the pole top fitter are self locking.
 Push cable through hole in pole and
 connect to connection box in base of pole.

Mounting on the Wall Plate


Make sure that the wall plate is sufficiently
 securely fixed to the installation surface.

Hang the luminaire onto the M10 x 40
 screws and tighten them with a torque of
 44 Nm. The threaded inserts in the wall
 plate are self locking. Insert the cable
 through the cable gland into the luminaire
 and then proceed with the electrical
 connection as mentioned above.

Mounting on other surfaces

Make sure that the installation surface is
 sufficiently stable and strong. To attach the
 luminaire, use at least 2 stainless steel M10
 screws of hardness 70. Take adequate
 precautions to prevent the screws from
 loosening. Make electrical connection as
 mentioned above.

The glass is toughened safety glass.



The light fitting may be operated only if all
 protective covers are in place.

Type	Weight	Projected area
8 272 3..	9,0 kg	0,11 m ²
8 271 3..	9,0 kg	0,11 m ²
8 273 3..	9,5 kg	0,11 m ²
8 274 3..	9,0 kg	0,11 m ²

Ensure that the minimum spacing between
 luminaire and illuminated surface is
 observed.

